



**MINI COUNTRYMAN: 1JXZ932**

Vinnumber:	<b>WMWZD31050WS24029</b>	Versionname:	<b>1.6 COOPER D</b>
First Registrationdate:	<b>17/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>114837</b>	Power Kw:	<b>82</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1228</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	<b>No Tow bar</b>
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**


Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>


**Degree of wear**

<b>205/55/17/95 V LightMetal</b>			
Summer tyres:	Fr.L. <b>Vredestein: 6 mm</b>	Fr.R. <b>Vredestein: 6 mm</b>	
	Re.L. <b>Michelin: 4 mm</b>	Re.R. <b>Michelin: 4 mm</b>	

**Assistance equipment**

Total cost ex VAT	<b>820,64</b>
Bonnet, Bad repair, Acceptable	<b>0,00</b>





Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68



Alloy rim F R, Deformed / Strained, E - Replace

235,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper moulding R, Bad repair, E - Replace

14,40



Door R L, Dent(s) and scratch(es), Acceptable

0,00

*No pictures to display*

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Windscreen, Stone chip(s), Windscreen repair

58,80



Door R R, Scratch(es), Acceptable

0,00

*No pictures to display*