



BMW 2 ACTIVE TOURER: 1KSJ232

Vinnumber:	WBA2B31060V542271	Versionname:	1.5 216D ACTIVE TOURER
First Registrationdate:	23/06/2015	Fiscalpower:	
Expertise Mileage:	181986	Power Kw:	85
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2711
Maintenance:	SERVICE IN 1900KM 6 2020		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2484,40
-------------------	----------------

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	292,18
---	---------------



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Dent(s), PDR - Paintless dent repair 130,80



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80





Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Sill trim L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Sill trim R, Scratch(es), LI - Repair and paint (complete) 310,50



Door F L, Dent(s), PDR - Paintless dent repair 63,00



Trunk lid covering R, Scratch(es), Smart repair 110,64



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 283,80



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display