



BMW 5: 1HG8901

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber: | WBA5C11080D034405 | Versionname: | 5 BER 518dA 136PK Aut. |
| First Registrationdate: | 11/07/2014 | Fiscalpower: | |
| Expertise Mileage: | 50231 | Power Kw: | 100 |
| Bodytype: | | Body color: | Silver |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4510 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Front parking sensors |
| Windows electric R | Rear parking sensors |
| Cruise Control | Type of Tow bar |
| Steering wheel multifunctional | No Tow bar |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting | Headlighting Xenon |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|---------------------|-------|---------------------|
| | 245/45/18/100 V LightMetal | | | |
| Winter tyres: | Fr.L. | Dunlop: 5 mm | Fr.R. | Dunlop: 5 mm |
| | Re.L. | Dunlop: 5 mm | Re.R. | Dunlop: 5 mm |

Assistance equipment

| | |
|--|----------|
| Number of charging cables (normal) | 0 |
| Number of charging cables (rapid charge) | 0 |

| | |
|--|---------------|
| Total cost ex VAT | 754,62 |
| Sill outer R, Scratch(es), LI - Repair and paint (complete) | 372,60 |



| | |
|--------------------------------|------|
| Wing R R, Repaired, Acceptable | 0,00 |
|--------------------------------|------|

No pictures to display

| | |
|---|--------|
| Door R R, Scratch(es), LI - Repair and paint (complete) | 382,02 |
|---|--------|

