



VOLVO XC90: FV2310

Vinnumber:	YV1LFA4BCG1009299	Versionname:	2.0 D5 4WD GEARTRONIC MOMENTUM 7PL.
First Registrationdate:	15/06/2015	Fiscalpower:	
Expertise Mileage:	116778	Power Kw:	165
Bodytype:	SUV	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3409
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/55/19/105 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2599,81
Door F L, Scratch(es), LI - Repair and paint (complete)	382,02



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Mirror side blinker L, Scratch(es), E - Replace 31,20



Wing trim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing moulding F L, Scratch(es), Le - Replace and paint 120,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper spoiler F, Scratch(es), E - Replace 48,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Wing trim R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing moulding F R, Deformed / Strained, Le - Replace and paint 120,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Rocker panel inner R L, Dent(s), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16





Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

264,21

