



VOLKSWAGEN Crafter 35 MWB: 1ALM797			
Vinnumber:	WV1ZZZ2FZA7003975	Versionname:	CRAFTER 35 LB2C MWB 109PK
First Registrationdate:	3/02/2011	Fiscalpower:	
Expertise Mileage:	150044	Power Kw:	80
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV06
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options			
Radio CD		Type of Tow bar	Tow bar fixed
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining artificial leather		
Type of climate control	No climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	235/65/16/115 R Steel			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment	
Spare wheel	Yes
Total cost ex VAT	1741,79
Seat cover R R, Hole, Smart repair	64,32



Wing F R, Deformed / Strained, Le - Replace and paint	427,51
---	---------------



Wing moulding F R, Missing, E - Replace 10,80



Seat cover F L, Stain, E - Replace 300,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Broken, E - Replace 74,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 232,88



Interior, Dirty, Cleaning 50,00



Sill outer L, Scratch(es), LI - Repair and paint (complete) 232,88



Bumper F, Scratch(es), Smart repair 110,64



Door R L, Rust, LI - Repair and paint (complete)

238,76

