



VOLVO XC60: 1LGK224

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber: | VV1DZARC1G2837579 | Versionname: | 2.0 D3 2WD VOLVO OCEAN RACE |
| First Registrationdate: | 22/09/2015 | Fiscalpower: | |
| Expertise Mileage: | 191519 | Power Kw: | 110 |
| Bodytype: | | Body color: | Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2327 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 4 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|----------------------|
| Radio CD | | Central consol F | |
| GPS storage | HD | Rear parking sensors | |
| GPS storage | | Type of Tow bar | Tow bar fixed |
| Windows electric F | | | |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |
| Level control | | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|--|-----------------------|-------|-----------------------|
| Winter tyres: | 235/60/18/107 WINTER H LightMetal | | | |
| | Fr.L. | Dunlop: 4 mm | Fr.R. | Dunlop: 4 mm |
| | Re.L. | Semperit: 4 mm | Re.R. | Semperit: 4 mm |
| | | | | |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|--------------------------|---------------|
| Total cost ex VAT | 788,36 |
|--------------------------|---------------|


| | |
|---|-------------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
|---|-------------|

No pictures to display

| | |
|--|-------------|
| Rocker panel inner R R, Scratch(es), Acceptable | 0,00 |
|--|-------------|

No pictures to display

| | |
|---|-------------|
| Alloy rim R R polished, Rust, Acceptable | 0,00 |
|---|-------------|

| | | |
|---|--|--------|
| <i>No pictures to display</i> | | |
| Rocker panel inner R L, Dent(s), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Steering wheel, Worn, Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Bumper F, Scratch(es), It - Spot repair | | 115,56 |
|  | | |
| Backrest cover F L, Worn, Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) | | 95,00 |
|  | | |
| Door F R, Dent(s) and scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Maintenance, Maintenance, Execute | | 0,00 |
|  | | |
| Rear bulkhead lining, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Rear window, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Alloy rim R L polished, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Door panel F L, Tear, Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Wing R L, Dent(s) and scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Moulding windscreen L, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Wing R R, Dent(s), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Door F L, Dent(s), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Roof, Scratch(es), LI - Repair and paint (complete) | | 577,80 |





Bumper R, Scratch(es), Acceptable

0,00

No pictures to display