



AUDI A3 SPORTBACK: 1KXL474

Vinnumber:	WAUZZZ8V4FA181105	Versionname:	1.6 TDI 81KW AMBIENTE
First Registrationdate:	24/07/2015	Fiscalpower:	
Expertise Mileage:	112982	Power Kw:	81
Bodytype:		Body color	LILA VIOLET
Gearbox:	MAN 6 VIT	Body color	Purple
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Maintenance	OK	Oil level	OK
Maintenance	SERVICE IN 6200KM 445D	Parking lot	4720
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	SD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 W LightMetal			
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------








Total cost ex VAT	1430,75
-------------------	----------------

Outer door handle F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Rear bulkhead lining, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof pillar L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Backrest cover F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
	
Bonnet, Chemical pollution, LI - Repair and paint (complete)	290,08
	
Alloy rim F R, Scratch(es), I - Repair	0,00
	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	356,20
	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Seat cover F L, Burned, Smart repair	64,32
	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Backrest cover F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door panel R R, Scratch(es), Acceptable

0,00

No pictures to display