



BMW 3 TOURING: 1KNL894

Vinnumber:	WBA3K31010F754221	Versionname:	2.0 320D (135KW) TOURING
First Registrationdate:	3/06/2015	Fiscalpower:	
Expertise Mileage:	119848	Power Kw:	135
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1408
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/18/91 Y LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1025,60
Wing F R, Bad repair, Acceptable	0,00



Door F R, Bad repair, Acceptable 0,00




Door R L, Bad repair, Acceptable 0,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Chemical pollution, Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Protection plate M, Deformed / Strained, E - Replace

84,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80




Tailgate, Scratch(es), LI - Repair and paint (complete)

0,00



Wing R R, Bad repair, Acceptable

0,00



Windscreen, Stone chip(s), Windscreen repair

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00





Door F L, Bad repair, Acceptable

0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Foglight R, Broken, E - Replace

138,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



