



IVECO DAILY: 1KPU239

Vinnumber:	ZCFC135CX05039611	Versionname:	
First Registrationdate:	11/06/2015	Fiscalpower:	
Expertise Mileage:	154259	Power Kw:	125
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV30
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/65/16/112 R Steel				
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Total cost ex VAT	3260,92
Door F R, Scratch(es), LI - Repair and paint (complete)	238,76



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Door moulding Lower F R, Missing, E - Replace 91,50



Door moulding Lower R L, Scratch(es), E - Replace 91,50



Wing F R, Scratch(es), LI - Repair and paint (complete) 165,13



Bumper F, Crack, Le - Replace and paint 575,25



Bumper corner R L, Scratch(es), Smart repair 110,64



Wheel aperture R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 200,00



Seat cover F L, Damaged, E - Replace 300,00



Wing trim R L, Scratch(es), E - Replace

69,00



Rearlight L, Scratch(es), E - Replace

91,50



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Rearlight R , Broken, E - Replace

91,50



Rearview mirror housing L, Scratch(es), Smart repair

110,64



Floor covering F L, Damaged, E - Replace

237,00



Wing F R, Scratch(es), It - Spot repair

115,56



Interior, Dirty, Cleaning

50,00





Bumper corner R R, Scratch(es), Smart repair

110,64

