



BMW 5: 1HCL606

Vinnumber:	WBA5J51070D582974	Versionname:	5 TOURING 520dXA 184PK Aut.
First Registrationdate:	18/06/2014	Fiscalpower:	
Expertise Mileage:	102710	Power Kw:	135
Bodytype:	Break	Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2228
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/101 Y LightMetal				
Summer tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Fulda: 5 mm	Re.R.	Fulda: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 2217,23

Rearview mirror basis L, Scratch(es), Smart repair 110,64



Door R R, Bad repair, Acceptable

0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Door F L, Scratch(es), LI - Repair and paint (complete)

382,02





Roof, Dent(s), PDR - Paintless dent repair 122,40



Sill outer L, Deformed / Strained, Forfeit 24,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete) 115,56





Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display


Rearview mirror basis R, Scratch(es), Smart repair 110,64



Bonnet, Chemical pollution, LI - Repair and paint (complete) 348,09



Wing R R, Bad repair, Acceptable 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



