


MERCEDES B: 1KGK471

Vinnumber:	WDD2462121J316244	Versionname:	1.5 B 180 CDI BLUEEFF STYLE EDITION
First Registrationdate:	28/04/2015	Fiscalpower:	
Expertise Mileage:	100522	Power Kw:	80
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	A 11300KM	Parking lot:	2829
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	No	Compressor	No
Total cost ex VAT			1869,41
Rearlight R , Broken, E - Replace			114,00



Roof pillar R, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Repaired, P - Check 0,00



Bumper R, Deformed / Strained, Le - Replace and paint 651,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Tyre repair kit, Missing, E - Replace 210,53



Bonnet, Hail damage, LI - Repair and paint (complete) 482,08



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Roof, Hail damage, PDR - Hail 200,00



Wing R R, Repaired, No repair 0,00

