



**OPEL Vivaro 2900: 1GPP767**

Vinnumber:	<b>WOLF7B1B1EV611101</b>	Versionname:	<b>VIVARO 2900 B/F MWB L2H1 DPF(EU5) 115PK</b>
First Registrationdate:	<b>26/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>144181</b>	Power Kw:	<b>84</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1205</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/65/16/107 T Steel</b>				
Summer tyres:	Fr.L.	<b>Goodyear: 6 mm</b>	Fr.R.	<b>Goodyear: 6 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>

**Assistance equipment**

Total cost ex VAT	1963,65
Bumper R, Scratch(es), E - Replace	329,40





Wing trim R R, Scratch(es), E - Replace

69,00



Door moulding Lower R R, Scratch(es), E - Replace

91,50



Seat cover F L, Hole, Smart repair

64,32



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Bumper F, Crack, E - Replace

398,40



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Interior, Dirty, Cleaning

50,00



Rocker panel inner F L, Dent(s), LI - Repair and paint (complete) 115,56



Seat cover F R, Dirty, Chemical cleaning 150,00



Bonnet, Stone chip(s), Acceptable 0,00

*No pictures to display*

Rocker panel inner F R, Scratch(es), Repair/replace (lump sum) 110,00



Trunk door R L, Dent(s) and scratch(es), It - Spot repair 115,56

