



FORD FOCUS CLIPPER: 1NXR729

Vinnumber:	WF06XXGCC6GG45998	Versionname:	1.5 TDCI 77KW S/S ECON 88G BUSINESS ED
First Registrationdate:	17/05/2016	Fiscalpower:	
Expertise Mileage:	79058	Power Kw:	77
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1106
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V Steel				
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Emergency spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	886,54
Trunk lid covering R, Scratch(es), Smart repair	110,64



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Wheel cover F R, Scratch(es), E - Replace

30,00



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Bad repair, Acceptable

0,00






Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Deformed / Strained, LI - Repair and paint (complete) 220,18



Bodywork, Glue residues, Acceptable 0,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Bumper corner R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s), PDR - Paintless dent repair 82,80



Rearview mirror housing L - Scratch(es), Acceptable 0,00

Head over him or heading 4, scratch(es), acceptable

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display