



BMW X3: 1JGR873

Vinnumber:	WBAWZ510X00L07667	Versionname:	X3 2.0dA xDrive20 163PK Aut.
First Registrationdate:	12/12/2014	Fiscalpower:	
Expertise Mileage:	154516	Power Kw:	120
Bodytype:	SUV	Body color:	Light Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2121
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/60/17/99 H LightMetal				
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1885,62
Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Rear spoiler, Chemical polution, LI - Repair and paint (complete) 115,56



Headlight R, Scratch(es), Acceptable 0,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00


No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16





Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof, Chemical pollution, Acceptable	0,00
--------------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display