



VOLVO V90: 1UFH069

Vinnumber:	VV1PW79B0J1063717	Versionname:	D3 Geartronic Momentum
First Registrationdate:	23/04/2018	Fiscalpower:	
Expertise Mileage:	29477	Power Kw:	110
Bodytype:	Break	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3209
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/100 Y LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1039,74
--------------------------	----------------

Wing R R, Repaired, Acceptable	0,00
---------------------------------------	-------------

<i>No pictures to display</i>	
Bonnet, Chemical polution, 67 - Polish	0,00

<i>No pictures to display</i>	
-------------------------------	--

Sill trim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), LI - Repair and paint (complete)	382,02
Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
Rear spoiler, Chemical polution, LI - Repair and paint (complete)	115,56
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Luggage space cover, Damaged, E - Replace	288,00