



**SKODA OCTAVIA COMBI: 1PBA337**

|                                    |                          |              |   |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber:                         | <b>TMBJG9NE4G0223726</b> | Versionname: | <b>1.6 CRTDI 81KW GREENTEC AMBITION</b> |
| First Registrationdate:            | <b>25/05/2016</b>        | Fiscalpower: |   |
| Expertise Mileage:                 | <b>163697</b>            | Power Kw:    | <b>81</b>                               |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                             |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                          |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Steel</b>                            |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                               |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>4104</b>                             |
| Maintenance:                       | <b>18290KM</b>           |              |   |
| Battery functioning:               | <b>Yes</b>               |              |   |
| Number of doors:                   | <b>5</b>                 |              |   |
| Number of seats:                   | <b>5</b>                 |              |   |
| Number head rests:                 | <b>5</b>                 |              |   |
| Rims summer:                       | <b>Steel</b>             |              |   |
| Category:                          | <b>Passenger Car</b>     |              |   |
| Oil level:                         | <b>OK</b>                |              |   |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |   |

**Options**

|                         |                              |                      |                          |
|-------------------------|------------------------------|----------------------|--------------------------|
| GPS storage             |                              | Central consol F     |                          |
| GPS storage             | <b>SD</b>                    | Luggage cover        |                          |
| Windows electric F      |                              | Rear parking sensors |                          |
| Windows electric R      |                              | Type of Tow bar      | <b>Tow bar removable</b> |
| Cruise Control          |                              |                      |                          |
| Seats F heated          |                              |                      |                          |
| Radio multimedia        |                              |                      |                          |
| Type of headlighting    | <b>Headlighting Halogen</b>  |                      |                          |
| Type of GPS             | <b>GPS big screen color</b>  |                      |                          |
| Type of Lining          | <b>Lining fabrics</b>        |                      |                          |
| Type of climate control | <b>Autom climate control</b> |                      |                          |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                             |       |                     |       |                     |
|-----------------------------|-------|---------------------|-------|---------------------|
| <b>205/55/16/91 V Steel</b> |       |                     |       |                     |
| Summer tyres:               | Fr.L. | <b>Dunlop: 4 mm</b> | Fr.R. | <b>Dunlop: 4 mm</b> |
|                             | Re.L. | <b>Dunlop: 5 mm</b> | Re.R. | <b>Dunlop: 5 mm</b> |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Emergency spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-----------------------|------------|------|------------|

|                   |                |
|-------------------|----------------|
| Total cost ex VAT | <b>1578,10</b> |
|-------------------|----------------|

|                                       |              |
|---------------------------------------|--------------|
| Wheel cover R L, Missing, E - Replace | <b>30,00</b> |
|---------------------------------------|--------------|



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wheel cover F L, Missing, E - Replace

30,00



Seat cover R R, Stain, Cleaning

25,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Door panel R R, Scratch(es), E - Replace

114,00



Door F R, Scratch(es), Acceptable

0,00



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Trunk lid covering R, Scratch(es), E - Replace

63,77



Bumper F, Dent(s) and scratch(es), Le - Replace and paint

0,00



Wing R R, Dent(s), PDR - Paintless dent repair

82,80



Wheel cover F R, Missing, E - Replace

30,00



Wheel cover R R, Missing, E - Replace

30,00



Headlight L, Broken, E - Replace

0,00



Door panel R L, Scratch(es), E - Replace

114,00



Bumper grille, Broken, E - Replace

0,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35

