



**RENAULT TALISMAN: 1SXC231**

|                                    |                          |              |                                  |
|------------------------------------|--------------------------|--------------|----------------------------------|
| Vinnumber:                         | <b>VF1RFD00558912725</b> | Versionname: | <b>Energy dCi 110 EDC Intens</b> |
| First Registrationdate:            | <b>4/08/2017</b>         | Fiscalpower: |                                  |
| Expertise Mileage:                 | <b>85153</b>             | Power Kw:    | <b>81</b>                        |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                      |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                   |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>                 |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                        |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1205</b>                      |
| Number of doors:                   | <b>4</b>                 |              |                                  |
| Number of seats:                   | <b>5</b>                 |              |                                  |
| Number head rests:                 | <b>5</b>                 |              |                                  |
| Rims summer:                       | <b>Aluminium</b>         |              |                                  |
| Category:                          | <b>Passenger Car</b>     |              |                                  |
| Oil level:                         | <b>OK</b>                |              |                                  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                  |

**Options**

|                                |                               |
|--------------------------------|-------------------------------|
| Radio CD                       | Central consol F              |
| Windows electric F             | Front parking sensors         |
| Windows electric R             | Rear parking sensors          |
| Cruise Control                 | Type of Tow bar               |
| Steering wheel multifunctional | <b>No Tow bar</b>             |
| Radio multimedia               |                               |
| Type of headlighting           | <b>Headlighting LED</b>       |
| Type of GPS                    | <b>GPS big screen color</b>   |
| Type of Lining                 | <b>Lining semi-leather</b>    |
| Type of climate control        | <b>Manual climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                   |       |                          |       |                          |
|-----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>225/55/17/101 W LightMetal</b> |       |                          |       |                          |
| Summer tyres:                     | Fr.L. | <b>Bridgestone: 5 mm</b> | Fr.R. | <b>Bridgestone: 5 mm</b> |
|                                   | Re.L. | <b>Bridgestone: 7 mm</b> | Re.R. | <b>Bridgestone: 7 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|   |        |
|---|--------|
| Total cost ex VAT   | 939,82 |
| Tailgate, Chemical polution, LI - Repair and paint (complete) | 362,02 |



