



VOLKSWAGEN Golf: 1HLY902			
Vinnumber:	WVWZZZAUZEW398126	Versionname:	GOLF BER Trendline 90PK
First Registrationdate:	25/08/2014	Fiscalpower:	
Expertise Mileage:	40124	Power Kw:	66
Bodytype:		Body color	Dark Blue
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4808
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Windows electric F		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	195/65/15/95 V Steel			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1668,07
Door R L, Scratch(es), LI - Repair and paint (complete)	318,35





Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Smart repair

110,64



Protection plate M, Deformed / Strained, E - Replace

74,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35





Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display