



VOLVO V60: 1KKG058

Vinnumber:	YV1FW74C1G1287769	Versionname:	1.6 D2 KINETIC
First Registrationdate:	20/05/2015	Fiscalpower:	
Expertise Mileage:	184336	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4410
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/97 V LightMetal				
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 3 mm	Re.R.	Vredestein: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	455,56
--------------------------	---------------






Bumper R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Centre console, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing R R, Dent(s), Acceptable	0,00
--------------------------------------	-------------

<i>No pictures to display</i>		
Sill outer L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Door panel R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door panel R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door panel F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Maintenance, Maintenance, Execute		0,00
		
Interior, Stain, Acceptable		0,00
<i>No pictures to display</i>		
Sunblind L, Broken, E - Replace		150,00
		
Door F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper F, Scratch(es), It - Spot repair		115,56
		
Door panel F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Rocker panel inner R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rear bulkhead lining, Scratch(es), Acceptable	0,00
---	------

No pictures to display