



OPEL Combo Cargo: 1HPN949			
Vinnumber:	WOL6VYC1AF9553453	Versionname:	COMBO COMBI SWB St/St(EU5)90PK
First Registrationdate:	5/09/2014	Fiscalpower:	
Expertise Mileage:	121055	Power Kw:	66
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2705
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	195/65/15/95 T Steel			
	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm
Winter tyres:	195/65/15/95 T Steel			
	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment	
Spare wheel	Yes Jack Yes
Total cost ex VAT	1057,97
Roof, Dent(s), LI - Repair and paint (complete)	361,13






Door R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 165,13



Sidewall panel RR, Missing, E - Replace 22,57



Door F L, Dent(s), PDR - Paintless dent repair 63,00



Wheel covers (all), Scratch(es), Acceptable 0,00

No pictures to display


Wheel cover F R, Scratch(es), E - Replace 22,50



Interior, Dirty, Cleaning 100,00



Door F R, Dent(s), PDR - Paintless dent repair 63,00



Molding trunk, Scratch(es), Acceptable 0,00

No pictures to display

Steering wheel, Worn, Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair 110,64



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

