


OPEL MOKKA: 1LKU293

Vinnumber:	W0LJD7EC5G4025899	Versionname:	1.6 CDTI 100KW AUTO COSMO
First Registrationdate:	14/10/2015	Fiscalpower:	
Expertise Mileage:	57368	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3312
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/18/92 H LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1081,10
Alloy rim R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bonnet, Chemical polution, LI - Repair and paint (complete)			290,08



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Bumper F, Scratch(es), Smart repair

110,64



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

307,80



Maintenance, Maintenance, Execute

0,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Wing moulding F L, Scratch(es), E - Replace

14,40



Foglight R, Broken, E - Replace

138,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display