



MERCEDES CLA: 1LBY329

Vinnumber:	WDD1173121N257380	Versionname:	1.5 CLA 180 CDI URBAN
First Registrationdate:	14/08/2015	Fiscalpower:	
Expertise Mileage:	108864	Power Kw:	80
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	BINNEN 36 DAGEN	Parking lot:	2306
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/17/91 W LightMetal				
Summer tyres:	Fr.L.	Yokohama: 5 mm	Fr.R.	Yokohama: 5 mm
	Re.L.	Yokohama: 6 mm	Re.R.	Yokohama: 6 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	506,56
-------------------	--------

Alloy rim F R polished, Rust, Acceptable	0,00
--	------

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair	82,80
--	-------



Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Seat cover F L, Tear, P - Check	0,00
---------------------------------	------

No pictures to display

Tailgate, Not original part, Sticker removal small	0,00
--	------

No pictures to display

Tailgate, Chemical pollution, 67 - Polish	0,00
---	------



Alloy rim F L polished, Rust, Acceptable	0,00
--	------

No pictures to display

Alloy rim R R polished, Rust, Acceptable	0,00
--	------

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Bumper corner R L, Scratch(es), It - Spot repair	115,56
--	--------



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R L polished, Rust, Acceptable	0,00
--	------

No pictures to display