



**VOLKSWAGEN TIGUAN: 1LDZ733**

Vinnumber:	WVGZZZ5NZFW515378	Versionname:	2.0 CRTDI 81KW SPORT & STYLE BMT
First Registrationdate:	6/02/2015	Fiscalpower:	
Expertise Mileage:	66207	Power Kw:	81
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2422
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

**Options**

Radio CD		Seats electric F L	
GPS storage		Sun Roof electric	
GPS storage	HD	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

**Limited Technical Inspection**

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

**Degree of wear**

Summer tyres:	215/60/17/96 V LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

**Assistance equipment**

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1391,83

Bumper cover R M, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Roof, Dent(s), Acceptable	0,00
No pictures to display	
Door R R, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Wheel hub cap R R, Broken, E - Replace	20,00



Door F R, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Wheel hub cap F R, Missing, E - Replace	20,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------





Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
---	--------



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F M, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door F L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display