


VOLKSWAGEN PASSAT: 1SPT690

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber: | WVWZZZ3CZFE508514 | Versionname: | 2.0 TDI HIGHLINE MSQ |
| First Registrationdate: | 1/06/2015 | Fiscalpower: | |
| Expertise Mileage: | 150623 | Power Kw: | 110 |
| Bodytype: | | Body color: | White |
| Gearbox: | Automatic | Paint type: | Metallic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3510 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|-------------------------------------|-----------------------|
| GPS storage | HD | Seats electric F L |
| GPS storage | | Seats electric F R |
| Windows electric F | | Central consol F |
| Windows electric R | | Luggage cover |
| Cruise Control | | Front parking sensors |
| Steering wheel multifunctional | | Rear parking sensors |
| Seats F heated | | |
| Type of headlighting | Headlighting Xenon | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining leather and alcantara | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-------------------------|-------|-------------------------|
| 215/55/17/94 Y LightMetal | | | | |
| Summer tyres: | Fr.L. | Vredestein: 5 mm | Fr.R. | Vredestein: 5 mm |
| | Re.L. | Vredestein: 7 mm | Re.R. | Vredestein: 7 mm |

Assistance equipment

| | | | |
|---|------------|------|---------------|
| Spare wheel | Yes | Jack | Yes |
| Total cost ex VAT | | | 827,80 |
| Alloy rim F R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Bumper F, Scratch(es), LI - Repair and paint (complete) | | | 211,80 |



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Side window trim R R, Missing, E - Replace

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Sill outer R, Scratch(es), It - Spot repair

0,00



Door R R, Scratch(es), LI - Repair and paint (complete)

0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

404,20

