



VOLKSWAGEN TOURAN: 1LUE169

Vinnnumber:	WVGZZZ1TZGW528400	Versionname:	1.6 TDI SCR 81KW BMT HIGHLINE
First Registrationdate:	7/12/2015	Fiscalpower:	
Expertise Mileage:	179890	Power Kw:	81
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	7400	Parking lot	3315
Maintenance	OK		
Maintenance	528 DAGEN		
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1002,70
Door frame R R, Dent(s), Acceptable			0,00

No pictures to display



Door frame R L, Scratch(es), It - Spot repair

115,56



Internal Boot Lining L, Scratch(es), Acceptable

0,00

No pictures to display

Maintenance book, Missing, E - Replace

0,00



Bumper R, Repaired, Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Dent(s), Acceptable

0,00

No pictures to display

Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Electricity circuit, Not functioning (well), Acceptable

0,00



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Door F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Internal Boot Lining R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Outer backrest protection R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), It - Spot repair

115,56





Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R L, Bad repair, LI - Repair and paint (complete)	0,00
--	------

