



PEUGEOT 308: 1HNG325

Vinnumber:	VF3LBBHXHES179029	Versionname:	308 BER BlueHDi Allure STT 116PK
First Registrationdate:	27/08/2014	Fiscalpower:	
Expertise Mileage:	116301	Power Kw:	85
Bodytype:	Hatchback	Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1327
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 8 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	900,00
Door R L, Dent(s), Acceptable	0,00
No pictures to display	
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display


Bumper cover R M, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)

0,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00






Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Bonnet, Chemical polution, 67 - Polish	0,00
No pictures to display	
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80



Wing R L, Chemical polution, LI - Repair and paint (complete)	308,20
---	--------



Wing F R, Scratch(es), Acceptable	0,00
No pictures to display	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
No pictures to display	
Ignition key, Missing, E - Replace	0,00
No pictures to display	
Wing R R, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	