


AUDI Q5: 1GGS319

Vinnumber:	WAUZZZ8R7EA076110	Versionname:	Q5 136PK
First Registrationdate:	4/02/2014	Fiscalpower:	
Expertise Mileage:	192770	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3512
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	DVD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/108 H LightMetal			
Winter tyres:	Fr.L.	Semperit: 2 mm	Fr.R.	Semperit: 2 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2036,37
-------------------	---------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Door panel F L, Scratch(es), Smart repair

110,64



Wing F L, Scratch(es), Acceptable

0,00



Bonnet, Chemical polution, LI - Repair and paint (complete)

348,09



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), Acceptable

0,00



Bumper cover R M, Scratch(es), Smart repair

110,64



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper F L, Scratch(es), Smart repair 110,64



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16




Roof, Chemical polution, 67 - Polish 0,00

No pictures to display

Engine protective plate, Deformed / Strained, E - Replace 74,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Boot cover, Broken, E - Replace 10,00





Protection plate M, Deformed / Strained, Acceptable

0,00

