


FIAT Doblo: 1CIM491

Vinnumber:	ZFA26300009128354	Versionname:	DOBLO CARGO SX 105PK
First Registrationdate:	6/12/2011	Fiscalpower:	
Expertise Mileage:	207905	Power Kw:	77
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1115
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 H Steel			
Summer tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Kleber: 6 mm	Re.R.	Kleber: 6 mm

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1360,19
Trunk door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Ignition key, Broken, E - Replace	150,00



Floor covering F L, Worn, Acceptable

0,00



Bonnet, Bad repair, Acceptable

0,00



Wheel cover F L, Broken, E - Replace

22,50



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Dent(s), Acceptable

0,00

No pictures to display

Door panel F L, Broken, E - Replace

91,50



Bumper R, Broken, E - Replace

329,40



Door R R, Dent(s), LI - Repair and paint (complete)

238,76



Bodywork, Not original part, Acceptable

0,00

No pictures to display

Wheel cover R R, Broken, E - Replace

22,50



Wing R L, Scratch(es), LI - Repair and paint (complete)

231,15



Wheel cover F R, Deformed / Strained, E - Replace

22,50





Reversible boot mat, Hole, Smart repair

64,32



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Trunk door R R, Dent(s) and scratch(es), It - Spot repair

187,56

