



AUDI A5 SPORTBACK: 1JTJ697

Vinnumber:	WAUZZZ8T4FA043319	Versionname:	2.0 TDI ULTRA 100KW
First Registrationdate:	20/02/2015	Fiscalpower:	
Expertise Mileage:	180205	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	MIN 200 KM	Parking lot:	4425
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1013,34
Trunk lid covering R, Scratch(es), Acceptable	0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Maintenance, Maintenance, Execute 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00



Bumper R, Dent(s), LI - Repair and paint (complete) 302,16



Rearview mirror housing L, Scratch(es), Acceptable 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00



Door R L, Scratch(es), Acceptable 0,00



Wing R L, Repaired, No repair 0,00



Tailgate, Bad repair, LI - Repair and paint (complete) 362,02



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Wing R R, Dent(s), Acceptable

0,00

