



BMW 3: 1HVS899

Vinnumber:	WBA3D110X0F395496	Versionname:	3 BER 318dA 136PK Aut.
First Registrationdate:	15/10/2014	Fiscalpower:	
Expertise Mileage:	69837	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2126
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Central consol F	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2553,43
--------------------------	----------------

Alloy rim F L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80




Door panel R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Tailgate, Scratch(es), Acceptable 0,00


No pictures to display



Bumper F, Scratch(es), LI - Repair and paint (complete)



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)



Wing R R, Dent(s) and scratch(es), Acceptable

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)



Door R L, Dent(s) and scratch(es), Acceptable

No pictures to display

Roof pillar L, Scratch(es), Acceptable

No pictures to display