


AUDI A4 AVANT: 1LKX534

Vinnumber:	WAUZZZ8K0FA183505	Versionname:	2.0 TDI ULTRA 100KW
First Registrationdate:	15/10/2015	Fiscalpower:	
Expertise Mileage:	125437	Power Kw:	100
Bodytype:		Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2414
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Emergency spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	2557,57
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)	115,56
---	--------



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	268,18
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display	
------------------------	--

GPS, Not functioning (well), Acceptable	0,00
---	------

No pictures to display	
------------------------	--

Door R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display	
------------------------	--

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display	
------------------------	--

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------





Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R R, Dent(s), LI - Repair and paint (complete) 115,56




Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Roof pillar L, Scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00




Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair

0,00



Rear spoiler, Scratch(es), LI - Repair and paint (complete)

115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

