



VOLVO XC60: 1HNS779

Vinnumber:	YV1DZ31A1F2658466	Versionname:	XC60 D3 Kinetic 136PK
First Registrationdate:	1/09/2014	Fiscalpower:	
Expertise Mileage:	142086	Power Kwr:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	10 MOIS OU 21.032 KM	Parking lot:	4214
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L	
TV/DVD screen R		Seats electric F R	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	235/60/18/107 V LightMetal			
	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	963,39
-------------------	---------------

Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Alloy rim R L polished, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Door R.D. Door(L). R.D.R. Paintless dent repair	63,00
---	--------------

Door R R, Dent(s), PDR - Paintless dent repair		63,00
		
Door F R, Scratch(es), LI - Repair and paint (complete)		382,02
		
Roof pillar R, Dent(s), Acceptable		0,00
No pictures to display		
Door F L, Scratch(es), Acceptable		0,00
No pictures to display		
Door R R, Scratch(es), Acceptable		0,00
No pictures to display		
Wing F R, Scratch(es), LI - Repair and paint (complete)		264,21
		
Bumper R, Scratch(es), LI - Repair and paint (complete)		254,16
		
Door R L, Dent(s) and scratch(es), Acceptable		0,00
No pictures to display		