



VOLVO XC90: 1LXU043

Vinnumber:	YV1LFBABDG1059954	Versionname:	2.0 T8 4WD GEARTRONIC R-DESIGN 7PL
First Registrationdate:	5/01/2016	Fiscalpower:	
Expertise Mileage:	186144	Power Kw:	235
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metallic
Transmission:	4 Weel	Rims summer	Aluminium
Fueltype:	Hybrid Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	4624
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	HD	Seats R heated	
GPS storage		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Central consol F	
Seats F heated		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	Headlighting LED	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	275/45/20/110 V LightMetal			
Winter tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2263,19
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing trim R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing moulding F L, Scratch(es), Le - Replace and paint 120,00



Tailgate, Scratch(es), Acceptable 0,00

Wing L, Scratch(es), Acceptable	0,00
No pictures to display	
Charging cable (normal), Missing, E - Replace	442,93
No pictures to display	
Door F L, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,16



Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Door F R, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), LI - Repair and paint (complete)	382,02



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------



Door R L, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00





Wing trim R R, Scratch(es), Le - Replace and paint

120,00



Charging cable (fast), Missing, E - Replace

309,92

No pictures to display