



VOLVO V60: 1HPL876

Vinnumber:	YV1FW8481F1228330	Versionname:	V60 BRE D2 Kinetic 115PK
First Registrationdate:	5/09/2014	Fiscalpower:	
Expertise Mileage:	96262	Power Kw:	84
Bodytype:		Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4412
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/60/16/96 H LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1432,78
Door panel F L, Tear, Smart repair	110,64




Bumper F, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00




Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Chemical polution, 67 - Polish	0,00
No pictures to display	
Door R R, Chemical polution, 67 - Polish	0,00
No pictures to display	
Ignition key, Missing, E - Replace	150,00
No pictures to display	
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Door F L, Scratch(es), Acceptable	0,00
No pictures to display	

Rocker panel inner F L, Dent(s), LI - Repair and paint (complete)		115,56
		
Wing R L, Scratch(es), Acceptable		0,00
No pictures to display		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Wing F L, Chemical polution, 67 - Polish		0,00
No pictures to display		
Roof, Chemical polution, LI - Repair and paint (complete)		481,50
		
Wing F R, Chemical polution, 67 - Polish		0,00
No pictures to display		
Alloy rim R L, Scratch(es), Acceptable		0,00
No pictures to display		
Door F R, Scratch(es), Acceptable		0,00
No pictures to display		