



VOLKSWAGEN GOLF VARIANT: 1LDH457

Vinnumber:	WVWZZZAUZFP600762	Versionname:	2.0 CR TDI HIGHLINE
First Registrationdate:	27/08/2015	Fiscalpower:	
Expertise Mileage:	190471	Power Kw:	110
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	IN 7200 KM	Parking lot	2205
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-Alcantara
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	BF Goodrich: 6 mm	Fr.R.	BF Goodrich: 6 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1237,92
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)			235,80



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

283,80



Door panel F L, Worn, Acceptable

0,00

No pictures to display

Seat cover R, Stain, Acceptable

0,00

No pictures to display

Door panel F L, Stain, Acceptable

0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Sill outer R, Dent(s), It - Spot repair

115,56



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display


Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Bad repair, E - Replace

487,20



Seat cover F R, Stain, Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56

