



BMW 3 BERLINE: 1LBR659

Vinnumber:	WBA8C31060K387455	Versionname:	2.0 318D (100KW) BERLINE
First Registrationdate:	12/08/2015	Fiscalpower:	
Expertise Mileage:	166908	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3532
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

225/55/16/95 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	4108,85
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Seat cover F L, Worn, Acceptable

0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display


Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00





Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper moulding F R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Chemical polution, LI - Repair and paint (complete)

220,18



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Tailgate, Chemical polution, LI - Repair and paint (complete)

301,68



Roof pillar R, Chemical polution, LI - Repair and paint (complete)

220,18

