



SEAT ALHAMBRA: 1KRD762

Vinnumber:	VSSZZ7NZFV524489	Versionname:	2.0 TDI CR 85KW REFERENCE ECOMOTIVE
First Registrationdate:	15/06/2015	Fiscalpower:	
Expertise Mileage:	130527	Power Kw:	85
Bodytype:	MPV	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1713
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 V Steel				
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	3322,32
Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display


Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 264,21



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 577,80



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Rear window, Scratch(es), Acceptable 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09





Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace 36,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Wheel cover F R, Scratch(es), E - Replace 36,00




Wheel cover R R, Scratch(es), E - Replace 36,00




Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84





Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02

