



VOLVO V60: 1LEH278

Vinnumber:	YV1FW78C0G1293926	Versionname:	2.0 D2 GEARTRONIC KINETIC
First Registrationdate:	4/09/2015	Fiscalpower:	
Expertise Mileage:	67492	Power Kw:	88
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3322
Maintenance:	IN 16801 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/97 H LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1161,60
Door panel R R, Hole, Smart repair	110,64



Seat cover F R, Stain, Cleaning 25,00



Ignition key, Missing, E - Replace 150,00



Bumper F, Scratch(es), It - Spot repair 115,56



Door R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display
Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display
Door R R, Scratch(es), 67 - Polish 0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 404,20



Seat cover F L, Stain, Acceptable 0,00

No pictures to display
Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 356,20



Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	