



VOLKSWAGEN GOLF VII: SF8434

Vinnumber:	VVWZZZAUZFW240955	Versionname:	1.6 TDI 77KW BMT TRENDLINE
First Registrationdate:	10/07/2015	Fiscalpower:	
Expertise Mileage:	181627	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4323
Maintenance:	BINNEN 16200 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

195/65/15/91 H Steel				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2008,74
Roof, Chemical polution, LI - Repair and paint (complete)	481,50



Seat cover F R, Stain, Cleaning

25,00



Rocker panel inner F L, Dent(s), Acceptable

0,00

No pictures to display

Backrest cover F L, Worn, Acceptable

0,00

No pictures to display

Rear Panel Internal Lining, Scratch(es), Smart repair

110,64



Rear window, Scratch(es), E - Replace

370,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Ignition key, Not functioning (well), Acceptable

0,00

No pictures to display

Windscreen, Crack, E - Replace


487,20



Trunk lid covering R, Scratch(es), Smart repair

110,64





Bumper F R, Scratch(es), It - Spot repair

115,56



Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display