



BMW 1 HATCH: JW7069

Vinnumber:	WBA1S51010V835471	Versionname:	2.0 118D (110KW)
First Registrationdate:	13/12/2016	Fiscalpower:	
Expertise Mileage:	75787	Power Kw:	110
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3824
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1404,50
-------------------	----------------

Ceiling, Burned, Smart repair	64,32
-------------------------------	--------------



Seat cover R, Stain, Cleaning

25,00



Roof, Chemical pollution, LI - Repair and paint (complete)

481,50



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Interior, Dirty, Chemical cleaning

24,00



Bonnet, Chemical pollution, LI - Repair and paint (complete)

290,08



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

307,80



Door R R, Bad repair, LI - Repair and paint (complete)

0,00



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Wing R R, Bad repair, LI - Repair and paint (complete) 0,00



Roof pillar R, Bad repair, LI - Repair and paint (complete) 0,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display