



BMW 3: 1HSB604

Vinnumber:	WBA3K11080F835589	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	18/09/2014	Fiscalpower:	
Expertise Mileage:	120862	Power Kw:	100
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4301
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	Tow bar fixed
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	410,50
-------------------	---------------

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	-------------



No pictures to display

Door R L, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

<i>No pictures to display</i>		
Rear bulkhead lining, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Rocker panel inner F L, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Door F R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Door panel R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Sill outer R, Scratch(es), LI - Repair and paint (complete)		310,50
		
Door panel F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Rocker panel inner F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Backrest cover F L, Worn, Acceptable		0,00
<i>No pictures to display</i>		
Door panel F R, Tear, Acceptable		0,00
<i>No pictures to display</i>		
Seat cover F L, Worn, Acceptable		0,00
<i>No pictures to display</i>		
Roof, Stone chip(s), Tu - Touch up		0,00
<i>No pictures to display</i>		
Bumper F, Bad repair, Acceptable		0,00
		
Bonnet, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Boot carpet, Chemical pollution, E - Replace		100,00

