


MERCEDES A: 1HYB097

Vinnumber:	WDD1760121V033509	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	27/10/2014	Fiscalpower:	
Expertise Mileage:	167095	Power Kw:	80
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4813
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	No	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	4318,69
Door panel R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Dent(s), PDR - Paintless dent repair	82,80




Trunk lid covering R, Scratch(es), Smart repair

110,64



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Interior, Dirty, Cleaning

100,00





Tyre repair kit, Missing, E - Replace 210,53



Windscreen, Stone chip(s), Windscreen repair 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Door panel R R, Hole, E - Replace 114,00



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete) 115,56



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 290,08



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display


Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 476,20





Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Speaker cover R L, Broken, E - Replace

42,00



Compressor, Missing, E - Replace

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)


211,80



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)

481,50





Alloy rim F L, Deformed / Strained, E - Replace

235,20

