



MERCEDES C COUP?: ZM8125

Vinnumber:	WDD2053401F629224	Versionname:	C 180 AMG Line
First Registrationdate:	5/10/2017	Fiscalpower:	
Expertise Mileage:	73739	Power Kw:	115
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Maintenance:	A5 DANS 6900 KMS	Parking lot:	1511
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	2		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	SD	Central consol F	
Windows electric F		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Alarm			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Level control			
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/18/95 Y LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			2516,67
Door F R, Scratch(es), LI - Repair and paint (complete)			318,35



Bumper grille F R, Scratch(es), E - Replace

32,40



Tyre F L, Tear, E - Replace

132,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)







307,80



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof pillar L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Glove compartment lid, Scratch(es), Smart repair	110,64
	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
	
Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear bulkhead lining, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tyre F R, Tear, E - Replace	132,00
	
Bumper moulding F R, Scratch(es), E - Replace	14,40
	
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper moulding F L, Scratch(es), E - Replace	14,40



Bodywork, Dirty, P - Check

0,00



Mirror side blinker R, Scratch(es), E - Replace

30,00



Interior, Dirty, Cleaning

150,00



Roof, Chemical pollution, Chemical cleaning

25,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

356,20



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display