



MERCEDES CLA 180 CDI: 1HRY441

Vinnumber:	WDD1173121N130430	Versionname:	CLA BER 180 CDI 109PK
First Registrationdate:	17/09/2014	Fiscalpower:	
Expertise Mileage:	151072	Power Kw:	80
Bodytype:		Body color:	Light Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3302
Maintenance:	A IN 354 DAYS		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Type of Tow bar	No Tow bar
Windows electric R		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining semi-leather	
Type of climate control	Manual climate control	
Level control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	225/40/18/92 V LightMetal			
	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	No	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1092,67

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

307,80



Wing R R, Scratch(es), It - Spot repair

115,56



Floor covering F L, Burned, Smart repair

64,32



Seat cover F L, Worn, Acceptable

0,00

No pictures to display

Sill trim R, Scratch(es), It - Spot repair

115,56



Tyre repair kit, Missing, Repair/replace (lump sum)

25,00



Interior, Waterinfiltration, P - Check

0,00



Covering interior A pillar L, Burned, E - Replace

46,08



Boot carpet, Damaged, E - Replace

100,00

