



**RENAULT Clio: 1HRB321**

Vinnumber:	<b>VF15RJL0H51404015</b>	Versionname:	<b>CLIO IV BER e-Business St&amp;St 90PK</b>
First Registrationdate:	<b>10/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>89349</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Red</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4629</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>HD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/65/15/88 T Steel</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>


**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>1872,94</b>
Door R R, Dent(s), PDR - Paintless dent repair	<b>63,00</b>



Bonnet, Chemical polution, LI - Repair and paint (complete) 232,06



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete) 115,56



Wing R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Trunk lid covering R, Scratch(es), Acceptable 0,00

*No pictures to display*

Wheel cover R R, Scratch(es), E - Replace 24,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Wing F L - Bad repair. Acceptable 0,00



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)

385,20



Wing F R, Chemical pollution, 67 - Polish

0,00

No pictures to display

Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Door R L, Repaired, Acceptable

0,00

No pictures to display

Door F L, Repaired, Acceptable

0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace

24,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44



Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Repaired, Acceptable

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68





Tailgate, Scratch(es), 67 - Polish 0,00

No pictures to display

Windscreen, Scratch(es), Acceptable 0,00



Rear window, Scratch(es), E - Replace 320,00

