



BMW 2 ACTIVE TOURER: 1LJR084

Vinnumber:	WBA2B31070V690896	Versionname:	1.5 216D ACTIVE TOURER
First Registrationdate:	6/10/2015	Fiscalpower:	
Expertise Mileage:	105272	Power Kw:	85
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4522
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1404,59
--------------------------	----------------

Ignition key, Worn, Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Outer backrest protection L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Door panel R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bumper R, Dent(s) and scratch(es), H. Repair and paint (complete)	244,00
--	---------------



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Armrest R M, Deformed / Strained, Acceptable 0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Tailgate, Dent(s), LI - Repair and paint (complete) 301,68



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), It - Spot repair 115,56



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Gear shift lever cover, Worn, Acceptable 0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 0,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Door R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door seal R L, Deformed / Strained, E - Replace 54,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Rearview mirror basis R, Scratch(es), Acceptable

0,00

No pictures to display

Outer backrest protection R, Scratch(es), Acceptable

0,00

No pictures to display