



SKODA FABIA COMBI: 1KUC026

Vinnumber:	TMBJJ6NJ2FZ070237	Versionname:	1.4 CRTDI 66KW AMBITION
First Registrationdate:	3/07/2015	Fiscalpower:	
Expertise Mileage:	103767	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4804
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/84 H Steel			
Summer tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1638,88
Internal Boot Lining L, Scratch(es), Smart repair	110,64





Wheel cover F R, Scratch(es), E - Replace

24,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68



Roof, Chemical polution, 67 - Polish

0,00

No pictures to display

Wing R L, Bad repair, Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Internal Boot Lining R, Scratch(es), Smart repair

110,64



Bonnet, Deformed / Strained, LI - Repair and paint (complete)

232,06





Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 24,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 169,44



Tailgate, Scratch(es), LI - Repair and paint (complete) 241,34



Door panel R L, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R R, Scratch(es), Smart repair 110,64



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), Acceptable 0,00



Luggage space cover, Missing, E - Replace 192,00

