



LAND ROVER RANGE ROVER SPORT: CM7014

Vinnumber:	SALWA2KF9GA553473	Versionname:	3.0 TDV6 190KW AUTO 4WD SE
First Registrationdate:	1/10/2015	Fiscalpower:	
Expertise Mileage:	159894	Power Kw:	190
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2213
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Level control			
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	255/55/20/110 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2486,52
-------------------	----------------

Door R R, Dent(s) and scratch(es), Le - Replace and paint	1107,49
---	----------------



Windscreen, Stone chip(s), Windscreen repair

58,80



Door moulding Lower F R, Scratch(es), E - Replace

132,00



Door moulding Lower R R, Crack, E - Replace

132,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete)

382,02



Bonnet, Chemical polution, LI - Repair and paint (complete)

348,09



Bumper R, Scratch(es), It - Spot repair

115,56



Bumper corner R R, Scratch(es), It - Spot repair

115,56



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display