


SKODA Octavia: 1HVX232

Vinnumber:	TMBJG7NE4F0095409	Versionname:	OCTAVIA COMBI Ambition 105PK
First Registrationdate:	16/10/2014	Fiscalpower:	
Expertise Mileage:	52939	Power Kw:	77
Bodytype:		Body color	Silver
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4816
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 V Steel			
	Fr.L.	Other: 4 mm	Fr.R.	Other: 4 mm
	Re.L.	Other: 5 mm	Re.R.	Other: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1121,82
Wheel cover R L, Scratch(es), E - Replace	30,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper grille, Broken, E - Replace

32,40



Bodywork, Not original part, Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display


Bumper cover R M, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Trunk lid covering R, Scratch(es), Acceptable


0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00
No pictures to display	
Roof, Chemical polution, LI - Repair and paint (complete)	481,50
	
Wheel cover F L, Scratch(es), E - Replace	30,00
	
Wheel cover F R, Scratch(es), E - Replace	30,00
	
Windscreen, Scratch(es), E - Replace	0,00
	
Floor covering F L, Hole, Smart repair	64,32
	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Bonnet, Chemical polution, 67 - Polish	0,00
No pictures to display	
Wheel cover R R, Scratch(es), E - Replace	30,00
	
Wing R L, Dent(s), Acceptable	0,00
No pictures to display	

no pictures to display