



**MERCEDES C BERLINE: 1RBV263**

Vinnumber:	<b>WDD2050361R227155</b>	Versionname:	<b>1.6 C 180 D AVANTGARDE</b>
First Registrationdate:	<b>8/11/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>37716</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>POOL 36</b>
Maintenance:	<b>UITVOEREN</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Sun Roof electric	
GPS storage	<b>SD</b>	Central consol F	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/50/17/94 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 6 mm</b>	Fr.R.	<b>Continental: 6 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	1972,64
Ceiling, Stain, Cleaning	25,00



Seat cover R, Damaged, E - Replace 360,00



Maintenance, Maintenance, Execute 0,00



Dashboard, Glue residues, Acceptable 0,00



Wing R L, Dent(s), LI - Repair and paint (complete) 428,20



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Roof, Chemical polution, 67 - Polish 0,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Hood, Scratch(es), LI - Repair and paint (complete) 290,08

Bumper, Scratch(es), LI - Repair and paint (complete)

230,00



Alloy rim R R polished, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L polished, Scratch(es), E - Replace

235,20



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00

